

Nr

A

B

C

D

E

F

G

H

I

J

K

L

M

N

O

P

R

S

T

U

V

W

X

Y

Z

DOLNOŚLĄSKIE

4160

1. Obiekt zabytkowy

DOM MIESZKALNY pl. Tadeusza Kościuski /Rynek /23/24

2. Miejscowość

Lewin Kłodzki

3. Wiek
XIX4. Styl
el. klas.5. Kubatura m³ 2370,06. Powierzchnia w m² 286,0
a) zabytkowa: b) użytkowa:

20. Przynależność administracyjna

a) województwo Wrocławskie

b) powiat Kłodzki

c) gmina Lewin

7. Materiał
budowlany

Przed zniszczeniem

Po odbudowie

11. Ilość budynków 1

14. Grunty należące do zabytku: ha

a) ściany

kamień

12. Ilość kondygnacji 2

a) ogrody stylowe

21. Stacja

Nazwa stacji

Odległość
od stacji
w km

b) sklepienia

cegła

13. Użytkowanie wnętrza
według ilości:

b) sady i grunty uprawne

a) kolejowa Lewin Kł.

c) stropy

drewno

a) izb mieszkalnych 9

c) lasy

b) autobusowa Lewin Kł.

d) wiązania
dachu

drewno

b) innych pomieszczeń

d) wody

22. Właściciel i jego adres

M Z B M Lewin Kłodzki

e) krycie dachu

łupek

c) piwnic 2

e) inne

8. Wyposażenie architektoniczne

portal, gzyms profilowany,
obramienia okien wykonane
w tynku

15. Przeznaczenie pierwotne budynku bud. mieszkalny

16. Użytkowanie w latach ubiegłych bud. mieszkalny

17. Użytkowanie obecne bud. mieszkalny

18. Nadaje się do użycia na

9. Autorzy i data budowy i przebudowy

Zbudowany w pocz. XIX w.

19. Data, rodzaj i stopień zniszczeń i odbudowy

Data	O P I S	Zniszczenia %	Odbudowa %
VIII. 1939 r.			
XI. 1939 r.			
XII. 1945 r.			
IV. 1969	stan dość dobry		

25. Rejestr zabytku Nr.....

rok..... miejsce przechowywania

26. Nazwa księgi hipotecznej

27. Nr hipoteczny

28. Akta

29. Fotografie


30. Inwentaryzacja pomiarowa

10. Udostępnienie

dostępny


gólnienie prac

gólnienie prac



Rzeczywiste


34. Inspekcje



Przewidywane

Rzeczywiste

34. Inspekcje

[illegible][illegible]

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. The left edge of the page shows the binding, with dark stitching or thread visible. There is no text or other markings on the page.



This image shows a single sheet of off-white or cream-colored paper. It features three horizontal blue lines spaced evenly apart, typical of notebook paper. The paper has a slightly textured appearance with some minor discoloration and faint smudges. There is no handwriting or other markings on the page.

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some minor discoloration and small dark spots, possibly foxing or dust. A faint rectangular outline is visible near the center of the page. The left edge of the page is bound with a dark, textured material, possibly leather or cloth.



A close-up photograph of a building's exterior. It features a window with a dark frame and a light-colored, possibly stone or concrete, wall. A dark, textured roofline is visible at the top of the frame.

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some minor discoloration and small dark spots, possibly due to age or handling. A faint horizontal line is visible near the top edge, suggesting a fold or a binding edge. The overall tone is warm and off-white.

36. Wypełnił



37. Sprawdził
IV. Og C

37. Sprawdził dnia

IV. Og Atobekuen

36. Wypełnił dnia

